

NOTICE of FILING

LAND USE REQUEST AFFECTING THIS AREA

There is a development proposal for the property listed in this notice and shown on the attached map. The City is seeking input from neighbors on the proposal. If you have questions or comments about the proposal, contact the case manager.

Esta carta es un aviso sobre una propuesta de desarrollo para la propiedad enumerada y que se muestra en el mapa adjunto. La ciudad está buscando la opinión de los vecinos sobre la propuesta. Si tiene preguntas o comentarios sobre la propuesta, póngase en contacto con nosotros al 503-588-6213.

CASE NUMBER: Class 2 Minor Historic Design Review Case No. HIS23-08

PROPERTY LOCATION: 1315 High St SE, Salem OR 97302

NOTICE MAILING DATE: June 2, 2023

PROPOSAL SUMMARY: A proposal to replace windows on the exterior of the Eder House (1918).

COMMENT PERIOD: All written comments must be submitted to City Staff no later than <u>5:00 p.m.</u>

Friday, June 16, 2023. Please direct any questions and/or comments to the Case Manager listed below. Comments received after the close of the comment period will not be considered. Note: Comments submitted are public record. This includes any personal information provided in your comment such as

name, email, physical address and phone number.

CASE MANAGER: Kimberli Fitzgerald, Historic Preservation Officer, City of Salem Planning

Division, 555 Liberty Street SE, Room 305, Salem, Oregon 97301. Telephone:

503-540-2397; E-mail: kfitzgerald@cityofsalem.net

NEIGHBORHOOD

ASSOCIATION:

Neighborhood associations are volunteer organizations of neighbors coming together to make neighborhoods the best they can be. They receive notice of land

use applications within their boundaries, and they often submit comments on the applications to the City. Neighborhood association meetings are open to everyone.

Contact your neighborhood association to get involved:

South Central Association of Neighbors (SCAN), Roz Shirack, Land Use Chair; Email: rozshirack7@gmail.com. South Central Association of Neighbors (SCAN),

Jon Christenson, Historic Preservation, Parks & Gardens, Chair, Email:

scanparks2023@gmail.com.

ACCESS: The Americans with Disabilities Act (ADA) accommodations will be provided on

request.

CRITERIA TO BE Salem Revised Code (SRC) Chapter(s) 230.025(b) – Windows

CONSIDERED:

Salem Revised Code (SRC) is available to view at this link:

http://bit.ly/salemorcode. Type in the chapter number(s) listed above to view the

applicable criteria.

PROPERTY OWNER(S): Patricia Sieg

APPLICANT(S): Patricia Sieg

PROPOSAL REQUEST: Class 2 Minor Historic Design Review of a proposal to replace nineteen (19)

windows on the secondary facades on the exterior of the Eder House (1918), a contributing resource within the Gaiety Hill/Bush's Pasture Park National Register Historic District, on property acres in .22 acres size, zoned RS (Single Family Residential), and located at 1315 High Street SE (Marion County Assessors Map

and Tax Lot number: 07327CD-1300).

APPLICATION PROCESS: Following the close of the Public Comment Period, a decision will be issued and

mailed to the applicant, property owner, affected neighborhood association, anyone who submitted written comments, and anyone who received notice of the

land use request.

Failure to raise an issue in writing prior to the close of the Public Comment Period

with sufficient specificity to provide the opportunity to respond to the issue, precludes appeal to the Land Use Board of Appeals (LUBA) on this issue. A similar failure to raise constitutional issues relating to proposed conditions of

onneval products on action for demands in circuit court

approval precludes an action for damages in circuit court.

MORE INFORMATION:All documents and evidence submitted by the applicant are available on the City's

online Permit Application Center at https://permits.cityofsalem.net. You can use the search function without registering and enter the permit number listed here: 23

108131. Paper copies can be obtained for a reasonable cost.

PLEASE PROMPTLY FORWARD A COPY OF THIS NOTICE TO ANY OTHER OWNER, TENANT OR LESSEE For more information about Planning in Salem:

http://www.cityofsalem.net/planning

It is the City of Salem's policy to assure that no person shall be discriminated against on the grounds of race, religion, color, sex, marital status, familial status, national origin, age, mental or physical disability, sexual orientation, gender identity and source of income, as provided by Salem Revised Code Chapter 97. The City of Salem also fully complies with Title VI of the Civil Rights Act of 1964, and related statutes and regulations, in all programs and activities. Disability-related modification or accommodation, including auxiliary aids or services, in order to participate in this meeting or event, are available upon request. Sign language and interpreters for languages other than English are also available upon request. To request such an accommodation or interpretation, contact the Community Development

Department at 503-588-6173 at least three business days before this meeting or event.

TTD/TTY telephone 503-588-6439 is also available 24/7

REQUEST FOR COMMENTS

Si necesita ayuda para comprender esta información, por favor llame 503-588-6173

REGARDING: Class 2 Minor Historic Design Review Case No. HIS23-08

PROJECT ADDRESS: 1315 High St SE, Salem OR 97302

AMANDA Application No.: 23-108131-PLN

COMMENT PERIOD ENDS: June 16, 2023

SUMMARY: A proposal to replace windows on the exterior of the Eder House (1918).

REQUEST: Class 2 Minor Historic Design Review of a proposal to replace nineteen (19) windows on the secondary facades on the exterior of the Eder House (1918), a contributing resource within the Gaiety Hill/Bush's Pasture Park National Register Historic District, on property acres in .22 acres size, zoned RS (Single Family Residential), and located at 1315 High Street SE (Marion County Assessors Map and Tax Lot number: 07327CD-1300).

The Planning Division is interested in hearing from you about the attached proposal. Staff will prepare a Decision that includes consideration of comments received during this comment period. We are interested in receiving pertinent, factual information such as neighborhood association recommendations and comments of affected property owners or residents. The complete case file, including all materials submitted by the applicant and any applicable professional studies such as traffic impact analysis, geologic assessments, and stormwater reports, are available upon request.

Comments received by <u>5:00 p.m. Friday</u>, <u>June 16, 2023</u>, will be considered in the decision process. Comments received after this date will be not considered. Comments submitted are <u>public record</u>. This includes any personal information provided in your comment such as name, email, physical address and phone number. <u>Mailed comments can take up to 7 calendar days to arrive at our office. To ensure that your comments are received by the deadline, we recommend that you e-mail your comments to the <u>Case Manager listed below</u>.</u>

<u>CASE MANAGER:</u> Kimberli Fitzgerald, Historic Preservation Officer, City of Salem, Planning Division; 555 Liberty St SE, Room 305, Salem, OR 97301; Phone: 503-540-2397; E-Mail: kfitzgerald@cityofsalem.net.

For information about Planning in Salem, please visit: http://www.cityofsalem.net/planning

IMPORTANT: IF YOU MAIL COMMENTS, PLEASE FOLD AND RETURN THIS POSTAGE-PAID FORM




BUSINESS REPLY MAIL FIRST-CLASS MAIL PERMIT NO. 1508 SALEM, OR

POSTAGE WILL BE PAID BY ADDRESSEE

PLANNING DIVISION CITY OF SALEM RM 305 555 LIBERTY ST SE SALEM OR 97301-9907 NO POSTAGE NECESSARY IF MAILED IN THE UNITED STATES

լանալույնին-ակարհրդիկինությունների ակարարակ**ն**

Vicinity Map 1315 High Street SE





1315 High Street SE - Site Plan




Case No.	

Historic Alteration Review Worksheet

Site Address: 1315 14161	1515E		
Resource Status: Contributing	Non- Contributing Inc	dividual Landmark □	
Type of Work Activity Proposed:	Major Minor		
Chose One: Commercial District Residential District	□ Individual Resource □	Public District	
Replacemen	t, Alteration, Restoration o	or Addition of:	
Architectural Feature:	Landscape Feature:	New:	
🛛 Awning	□ Fence	☐ Addition	
□ Door	□ Streetscape	☐ Accessory Structure	
□ Exterior Trim, Lintel	☐ Other Site feature (describe)	□ Sign	
□ Other architectural feature		□ Mural	
□ Roof/Cornice		□ Accessibility Ramp	
□ Masonry/Siding		☐ Energy Improvements	
☐ Storefront		☐ Mechanical Equipment	
M Window(s) Number of windows: 19		□ Primary Structure	
HLC clearly understand the proposed wo	work proposed. Describe how it mal information (i.e., product specifiork:	eets the applicable design criteria in SRC ication sheets) that will help staff and the	
Materials are paintable and Rot Resistant. Class to be replaced with			
energy efficient clouble pane. Finished product will Look the Same			
as the original excep	tscreens will bei	nside.	
Patricia Sing	~	04/13/22	
Signature of Applicant		Date Submitted/Signed	
City of Salem Permit Application Center -	- 555 Liberty Street SE / Room 32	0 – Salem, OR 97301 / (503) 588-6213	

Building Sketch

Borrower/C	lent Sieg, Thomas & Patricia			
Property Ad	dress 1315 High St SE			
City	Salem	County Marion	State OR	Zlp Code 97302
Lender	U.S. Bank N.A.			



Comments:

41.2	AREA CALCULAT					rea Breakd	
Code	Description	Net Size	Net Totals	Bre	eakdo	rivin	Subtotals
GLA1	First Floor	1973,00	1973.00	First Floor			i
GLA2	Second Floor	970.00	970.00		x	12.0	432,00
BSMT	UnfinBasement	1332.00	1332.00		×	3.0	120.00
			İ		x	39.0	39.00
					x	43.0	344.00
					x	15.0	570.00
				13.0	x	36.0	468,00
				Second Floor			i
					x	18.0	648.00
				23.0	x	14.0	322.00
N€	et L!VABLE Area	(rounded)	2943	8 Items		(rounded)	2943




Renewal by Andersen will be performing window replacement at 1315 High St SE Salem OR 97302. The house has old wooden windows which are in need of replacing. On homes like this we custom make our windows to be exactly like the originals. We perform a retrofit installation in which we retain all of the original exterior trim as well as the original interior trim on the home. The windows we will install on this home will be our red rock color so should look very similar to the originals. We will be replacing all of the windows in the upstairs which are all on the back of the house and the sides. We will also be replacing the basement windows.

The windows that we use are a wood composite material. We do not use a vinyl product or any wood clad product because the exterior appearance of these windows looks like plastic and the windows fail due to poor quality. Our wood composite material is painted so it looks exactly like a painted wood window and it is also waterproof and will never rot or bow and will not need replacing. On windows which have exterior grids or muntins we do full divided lite grids which are permanently attached to the window just like the originals.

We have done many houses just like this and some quite a bit older and more historic.

Here are some good examples below. The windows in the first image are on an old schoolhouse. The windows you see on the bottom were not done yet and are the originals. The windows on the top floor are our windows.



This Victorian Queen Anne house also has the red rock color windows we will be installing. These are all our wood composite windows even the small one next to the entry door.

Window Assessment – Exterior

Date:

Building: 1315 HIGH StSE

,	Location: North BASEMENT
	Window Description: Hopper Style Opens In. Sealled Stut. Single pane X3
	Sill: Far - Some Rot In Remove paint Repair
	Replace
	Frame/Trim:
	Remove paint
	Repair
	Replace
	Sash/Muntins/Leading:
	Remove paint
	Repair
	Replace
	Glazing Putty:
	% to repair
	% to replace
Dimensions of window: 47.5 x 21.5	
Frame = 18,5 x40	Glazing:
Each Pane= 11x13	Old
	New
	Broken
Remarks: Water Comes in Through This Window.	Hardware Description:
Thes Window.	Remove paint
	Missing

${\bf Window\ Assessment-Interior}$

Date: 4/2/2023 Building: 1315 HiGH St SE

water Intrusion between	Location: North Basement
concrete and sill and	Window Description: Hopper Style
between rail & Frame	opens Inward wood unpainted Single Pand 3 panes - Fixed Shut.
	3 panes- Fixed Shut.
	Stool: Fair to Poor
	Remove paint
	Repair
	Replace
	Frame/Pulley/Stiles:
	Remove paint
	Repair
	Replace
	Sush/Muntins/Leading:
	Remove paint
	Repair
	Replace
	Trim: None
The state of the s	Remove paint
The second secon	Repair
	Replace
Dimensions of window:	
47.5 x 21.5	Hardware Description: Sash lock
Frame = 18.5 × 40	Remove paint No Paint
	Missing Hingls at top
3Panes@ 11×13	Ropes/Chains: None
	Replace
Remarks: Change to Double pane Sliding Window. Replace Frame	
Suding Window. Keplace Frame	Weatherstripping: NONE
Sill & Rails.	Replace

$Window\ Assessment-Exterior$

Date: 4/2/2023 Building: 1315 HiGH St SE

	Location: 2.09 Story		
	South bedroom		
	Window Description: Single pane bank 084 Casements opening in.		
	Aluminum Stame Screed &		
	RAIN BINETE Pat base of Frame		
	Sill: far		
	Remove paint		
	Repair		
	Replace		
	Frame/Trim: PCO		
	Remove paint		
	Repair		
	Replace		
	Sash/Muntins/Leading:		
	Remove paint		
Rain	Repair		
diverter	Replace		
	Glazing Putty: 6-00 / Fair		
	% to repair		
	% to replace		
Dimensions of window:			
113 x50	Glazing:		
113 X50 4 panes & Frames at 40 X24 rack	☑ Old		
r l	New		
	Broken		
Remarks: 2 Center windows are tixed shut. 2 outer ones wont shut, or the wind shakes the hardware until	Hardware Description:		
In a wind snake the hardware until	Remove paint		
	Missing		
point caused dry rot below the Apron. Awning is Rotting & has hole starting	*		
The state of the s			

$Window\ Assessment-Interior$

Date:

Building: 1315 HiGH St

	Location: South - Ball		
	Window Description: Wood CHSement-Opens Inward Single Pane		
	Stool: Cod		
	Remove paint		
	Repair		
	Replace		
	Frame/Pulley/Stiles: 600 C		
	Remove paint		
	Repair		
	Replace		
	Sash/Muntins/Leading: 6-606		
	Remove paint		
	Repair		
	Replace		
	Trim: C-Cod		
	Remove paint		
	Repair		
	Replace		
Dimensions of window: 37 × 33 -	W. D		
Windows Frame - 28 x 24	Hardware Description: Cood Remove paint South Lock		
Windows France - 2010	phomeny		
	Missing		
	Ropes/Chains: NONG		
window in good chape would	Replace		
Remarks: Replace to the consistent age of material on two floor. Remove & Replace Aluminum Frame Storm/screen Windows			
Remove & Replace Aluminum Frame	Weatherstripping: Word		
Storm/screen windows	Replace		